

NA - Not Available
 F - Friable
 SM - Surfacing Material

NF - Non-Friable
 SFP - Stop @ first positive. Sample not analyzed.
 TSI - Thermal Systems Insulation

HM No.	Description	Photo No.	Material Location	Sar N
1	Floor Tile 12"x12" White (tile and mastic)	--	1 st Floor rooms 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 113, 114, 115, 116, 117, 118, 118A, 119, 120 and Corridor 100	
2	Ceiling tile, 1'x1' (glued on) grooved		N/A	
3	Pipe fitting insulation on cardboard-type straight runs		Domestic water systems insulation in crawl space and inaccessible to walls	
4	Pipe insulation, aircell-type		Steam systems insulation in crawl space and inaccessible in walls	
5	Pipe insulation, cardboard-type		Domestic water systems insulation in crawl space. Inaccessible in walls.	
6	Tank insulation		Mechanical room	
7	Plaster, radiator heat shields		N/A	
8	Contaminated soil		Crawl space	
9	Plaster, finish on concrete		1 st floor, all interior walls	

Sample Number	Sample Location	%	F / NF	Cond	Est. Qty.	Abatement Cost	Replacement Cost	Comment
			NF	Good	5,350 SF on first floor	\$16,050		
					0			
			F	Good	115 each in crawl space	\$3,450		
					15 each on first floor	\$450		
			F	Good	750 LF in crawl space	\$22,500		
					250 LF on first floor	\$7,500		
					0			
			F	Good	60 SF on basement floor	\$180		
					0			
					5,250 in crawlspace			
					0			